
-39

DART AEROSPACE LTD	Work Order:	21408		
Description: Washer	Part Number:	D3137-5		
Dwg: D3137 Rev. D	Qty:	HQ 47		
		Page 1 of 1		

Step	Location	Procedure	Ву	Date	Qty
1	DC	Issue Traveler	#	04.11.04	40
2	МС	Machine as per Folio FA471 and Dwg D3137 Material: 6061-T6 (QQ-A-225/8 or QQ-A-200/8) 0.750" Bar (M6061T6R0.750) Identify as D3137-5 Batch: MISIAL	Test	of 11.04	40.
3	QC2	Inspect parts as they come off the CNC machine		4.11.04	40.
4	QC8	Second check	G	04.11.04	40
5	MC	Deburr	201	04.11.04	40
6	FP	Chemical Conversion Coat as per QSI 005 4.1	M	rd 11 08	40
7	QC3	Inspect Chemical Conversion Coat	2	C4-11-09	40
8	QC5	Inspect work to Step 7	A	0411110	40
9	ST	Identify and Stock	ĊŽ	01/11/10	42
10	AC	Cost / part / 85	540	04-11/11	SP
11	DC	Close W/O Z , / 4/ Inspect Level 21	4	04,11,11	42


Rev	Date	Change	Revised By	Approved
Α	04.11.04	New issue	KJ/JLM	11/



Dart Aerospace Ltd

W/O:			WO	RK ORDER CHANGE	S				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approva QC Inspector
			*						
NCR:			WORK ORDE	R NON-CONFORMAN	ICE (NCF	2)			
DATE SI	CTED	TEP Description of NC Section A	Corrective Action Section B			Verific		Approval	Approval
	SIEP		Initial Design Mgr	Action Description Design Mgr	Sign 8 Date		Section C	Design Mgr	QC Inspecto
		,							
				·				11	
							•		
Part No	o:	PAR #:	Fault Category	:NCR:	Yes No	DQA:		Date:	
NOTE: D	ate & initia	al all entries			QA: N/C CI	osed:		Date:	·

DESIGN	DRAWN BY		EROSPACE LTD BURY, ONTARIO, CANADA			
CHECKED	APPROVED	DRAWING NO.	REV. D SHEET 3 OF 4			
DATE	l	TITLE	SCALE			
04.11.03		BRACKET ASSEMBLY	1:1			



D3137-3 GUIDE

REPLACES PREMIER P/N B30-23000-207

MATERIAL: DELRIN BAR (REF DART SPEC. M-DELRIN-B)

3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHÉRWISE NOTED

ALL DIMENSIONS ARE IN INCHES

5) BREAK ALL EDGES 0.005 TO 0.015


UNCONTROLLED COPY


SUIJEST TO AMENDMENT WITHOUT NOTICE

WORK ORDER

R0.125 NO. 21408 (4 PLACES)

PRELIMINARY ISSUE





D3137-5 WASHER

- 1) REPLACES PREMIER P/N B30-23000-209
- MATERIAL: 6061-T6 (QQ-A-225/8 OR QQ-A-200/8) BAR (REF DART SPEC. M6061T6R)
- FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- ALL DIMENSIONS ARE IN INCHES
- BREAK ALL EDGES 0.005 TO 0.015

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Job Costing Report

Dart	Aerospace	Ltd.
Hawke	esbury	

Aug 30, 2004 07:28 am

Work Order No : 0021408 Project Name : D3137-5

Project For : WK439

Work Order Type : Main Main WO Number :

House Part Number: D3137-5 Description : Washer

Manufactured : No

Amount Req'd:

Amount Done : Start Date : 08-27-04

Est Finish Date : 09-23-04

Act Finish Date : Drawings Regd : No Ok for Approval :

Approval Rec'd :

Department Code:

Burden Flags : NNNNNNN WO Status : Open

Invoice State : Not Invoiced

Invoice Date :

Invoice Number :

Invoice Amount : 0.00

Order Entry No :

OE Value : 0.00

Est Margin : 0.000% Actual Margin : 0.000%

\$0 Posted to Finished Goods

		Estimated	Actual	Var. %	Posted	To Post
Material Cost	=== :	0.00	0.00	0.00	0.00	0.00
Engineering Hours	:	0.00	0.00	0.00		
Engineering Cost	:	0.00	0.00	0.00	0.00	0.00
Production Hours	:	0.00	0.00	0.00		
Production Cost	:	0.00	0.00	0.00	0.00	0.00
Packaging Hours	:	0.00	0.00	0.00		
Packaging Cost	:	0.00	0.00	0.00	0.00	0.00
OverHead Hours	:	0.00	0.00	0.00		
OverHead Cost	:	0.00	0.00	0.00	0.00	0.00
CNC Hours	:	0.00	0.00	0.00		
CNC	:	0.00	0.00	0.00	0.00	0.00
Misc. Hours	:	0.00	0.00	0.00		
Misc.	:	0.00	0.00	0.00	0.00	0.00
		=======	=======	======		
Burden	:	0.00	0.00	0.00		
		========	========	======		
Total Cost	:	0.00	0.00	0.00		
Margin	:	0.000	0.000			
Selling Cost	:	0.00	0.00			

Estimated Actual 0.00 0.00 Labour Hrs/Amount Done : 0.00 0.00 Profits/(Loss)

DART AEROSPACE LTD	Work Order:	21408 -
Description: Washer.	Part Number:	03/37-5
Inspection Dwg: D3/37- Rev: D		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST									
		First Artic	le 🕏	Prot	otype				
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method Inspect	T.	Comments		
,740.	+/.010	\$745							
\$ 257	1.005	\$.253							
\$ 500x 100 "	@+/-010	\$ 507							
8.360		7.360		· · · · · · · · · · · · · · · · · · ·					
\$ 660	1-010	.657							
0080	4-010	-081							
.200	4/-010.	.24							
		,							
				• • • • • • • • • • • • • • • • • • • •					
							4-19		
									
			· · · · · · · · · · · · · · · · · · ·	······································					
Measured by:	Measured by: Audited by: Prototype Approval:								
Date:	4.11.04		H-11-08		Date: 04.11.				
Rev Date	Change /	***				Revised			
A	New Issue				······································	KJ/RF			